

DILL TPMS APPLICATIONS CHART ©

OE	Model	Model Year	Torque In-Lbs	Dill Kit #	Costco Service Pack #	Valve Stem Replacement	Costco Valve #	Dill Sensor	Costco Sensor #
Acura	CSX	08-11	35	2040K	502971	NO	NO	7002	707597
Acura	ILX	13	71	7000K	502973	VS70	707594	7002	707597
Acura	MDX	04-06	35	1096	300415	1096	300415	1057	503013
Acura	MDX	07-12	35	1100K	502921	NO	NO	1209	574590
Acura	MDX	13	71	7020K	648487	VS70	707594	5512	N/A
Acura	RDX	07-12	35	1100K	502921	NO	NO	1209	574590
Acura	RDX	13-14	71	7020K	648487	VS70	707594	5512	N/A
Acura	RL	05-08	35	1096	300415	1096	300415	1057	503013
Acura	RL	09-12	35	2040K or 2000K	502971 OR 502927	NO OR 1096	NO OR 300415	1057	503013
Acura	RLX	13-14	35	2040K	502971	NO	NO	1214	574251
Acura	TL	05-08	35	1096	300415	1096	300415	1057	503013
Acura	TL(Hi-Line)	09-13	35	2040K	502971	NO	NO	1214	574251
Acura	TSX	07-13	35	1100K	502921	NO	NO	1209	N/A
Acura	ZDX(Hi-Line)	10-13	35	2040K	502971	NO	NO	1214	574251
Audi	Allroad(315 Mhz)	01-05	35	1090K	502980	1092	502980	9004	489773
Audi	A6 Allroad(433 Mhz)	01-06	35	1090K	502980	1092	502980	9001	545608
Audi	A6 Allroad(433 Mhz)	07-09	35	1090K	502980	1092	502980	9007	571724
Audi	A6 Allroad(433 Mhz)-- Post June 2009	10	35	1090K	502980	1092	502980	9011	574593
Audi	A3(315 Mhz)	06-12	71	1030K	502902	NO	NO	1053	506565
Audi	A4(433 Mhz)	05-08	35	1090K	502980	1092	502980	9007	571724
Audi	A4 (315 Mhz)	09-11	71	1030K	502902	NO	NO	1053	506565
Audi	A5(315 Mhz)	08-11	71	1030K	502902	NO	NO	1053	506565
Audi	A6(315 Mhz)	02-04	35	1090K	502980	1092	502980	9004	489773
Audi	A6(433 Mhz)	05-09	35	1090K	502980	1092	502980	9007	571724
Audi	A6(433 Mhz)-- Post June 2009	10-11	35	1090K	502980	1092	502980	9011	574593
Audi	A8(315 Mhz)	00-07	35	1090K	502980	1092	502980	9004	489773
Audi	A8(433 Mhz)	00-12	35	1090K	502980	1092	502980	9001	545608
Audi	Q5(315 Mhz)	09-12	71	1030K	502902	NO	NO	1053	506565
Audi	Q7(433 Mhz)	06-09	35	1090K	502980	1092	502980	9007	571724
Audi	Q7(433 Mhz)-- Post June 2009	10-12	35	1090K	502980	1092	502980	9011	574593
Audi	R8(433 Mhz)	08-09	35	1090K	502980	1092	502980	9007	571724
Audi	R8(433 Mhz)-- Post June 2009	10-11	35	1090K	502980	1092	502980	9011	574593
Audi	RS4(433 Mhz)	07-08	35	1090K	502980	1092	502980	9007	571724
Audi	RS6(315 Mhz)	01-05	35	1090K	502980	1092	502980	9004	489773
Audi	RS6(433 Mhz)	01-04	35	1090K	502980	1092	502980	9001	545608
Audi	S4(433 Mhz)	05-09	35	1090K	502980	1092	502980	9007	571724
Audi	S4(315 Mhz)	10-11	71	1030K	502902	NO	NO	1053	506565
Audi	S5(315 Mhz)	08-12	71	1030K	502902	NO	NO	1053	506565
Audi	S6(433 Mhz)	05-09	35	1090K	502980	1092	502980	9007	571724
Audi	S6(433 Mhz)-- Post June 2009	10-11	35	1090K	502980	1092	502980	9011	574593
Audi	S8(315 Mhz)	00-08	35	1090K	502980	1092	502980	9004	489773
Audi	S8(433 Mhz)	00-09	35	1090K	502980	1092	502980	9001	545608
Audi	TT(315 Mhz)	08-12	71	1030K	502902	NO	NO	1053	506565
Bentley	Continental GT--433 Mhz	03-05	35	1090K	502980	1092-1095	502980, 502981, 502992, or 502997	9001	545608
Bentley	Continental GT--433 Mhz (Post May)	05-14	35	1090K	502980	1092-1095	502980, 502981, 502992, or 502997	9007	571724
Bentley	Azure--433 Mhz	07-14	35	1090K	502980	1092-1095	502980, 502981, 502992, or 502997	9007	571724
Bentley	Mulsanne--433 Mhz	11-14	35	1090K	502980	1092-1095	502980, 502981, 502992, or 502997	9007	571724
Bentley	Flying Spur--433 Mhz	06-14	35	1090K	502980	1092-1095	502980, 502981, 502992, or 502997	9007	571724
BMW	1 Series(433 Mhz)	07-10	35	1090K	502980	1092-1095	502980, 502981, 502992, or 502997	1027	562514

DILL TPMS APPLICATIONS CHART ©

OE	Model	Model Year	Torque In-Lbs	Dill Kit #	Costco Service Pack #	Valve Stem Replacement	Costco Valve #	Dill Sensor	Costco Sensor #
BMW	1 Series(433 Mhz)-- September, 2010	11-13	35	1096	300415	1096	300415	9012	574594
BMW	3 Series(315 Mhz)	00-02	35	1090K	502980	1092-1095	502980, 502981, 502992, or 502997	9004	489773
BMW	3 Series(433 Mhz)	00-04	35	1090K	502980	1092-1095	502980, 502981, 502992, or 502997	9002	573806
BMW	3 Series(433 Mhz)	07-10	35	1090K	502980	1092-1095	502980, 502981, 502992, or 502997	1027	562514
BMW	3 Series(433 Mhz)-- September 2009	10-12	35	1096	300415	1096	300415	9012	574594
BMW	3-series	13-14	35	1096	300415	1096	300415	9017	728984
BMW	5 Series(315 Mhz)	00-02	35	1090K	502980	1092-1095	502980, 502981, 502992, or 502997	9004	489773
BMW	5 Series(433 Mhz)	02-05	35	1090K	502980	1092-1095	502980, 502981, 502992, or 502997	9002	573806
BMW	5 Series(433 Mhz)	06-10	35	1090K	502980	1092-1095	502980, 502981, 502992, or 502997	1027	562514
BMW	5 Series(433 Mhz)-- September, 2010	11-13	35	1096	300415	1096	300415	9012	574594
BMW	6 Series(433 Mhz)	06-13	35	1090K	502980	1092-1095	502980, 502981, 502992, or 502997	1027	562514
BMW	7 Series(315 Mhz)	00-01	35	1090K	502980	1092-1095	502980, 502981, 502992, or 502997	9004	489773
BMW	7 Series(433 Mhz)	02-05	35	1090K	502980	1092-1095	502980, 502981, 502992, or 502997	9002	573806
BMW	7 Series(433 Mhz)	06-10	35	1090K	502980	1092-1095	502980, 502981, 502992, or 502997	1027	562514
BMW	7 Series(433 Mhz)-- September, 2010	11-13	35	1096	300415	1096	300415	9012	574594
BMW	M Series(433 Mhz)	06-10	35	1090K	502980	1092-1095	502980, 502981, 502992, or 502997	1027	562514
BMW	M Series(433 Mhz)-- September 2009	11-13	35	1096	300415	1096	300415	9012	574594
BMW	X1	12-14	35	1096	300415	1096	300415	9012	574594
BMW	X3(433 Mhz)	06-10	35	1090K	502980	1092-1095	502980, 502981, 502992, or 502997	1027	562514
BMW	X3(433 Mhz)	11-14	35	1096	300415	1096	300415	9012	574594
BMW	X5(433 Mhz)	01-04	35	1090K	502980	1092-1095	502980, 502981, 502992, or 502997	9003	661042
BMW	X5(433 Mhz)	05-10	35	1090K	502980	1092-1095	502980, 502981, 502992, or 502997	1027	562514
BMW	X5(433 Mhz)-- October, 2010	11-13	35	1096	300415	1096	300415	9012	574594
BMW	X6(433 Mhz)	08-11	35	1090K	502980	1092-1095	502980, 502981, 502992, or 502997	1027	562514
BMW	X6(433 Mhz)-- October, 2010	11-13	35	1096	300415	1096	300415	9012	574594
BMW	Z Series(433 Mhz)	06-10	35	1090K	502980	1092-1095	502980, 502981, 502992, or 502997	1027	562514
BMW	Z Series(433 Mhz)-- September 2009	11-13	35	1096	300415	1096	300415	9012	574594
BMW	Alpina(433 Mhz)	07-08	35	1090K	502980	1092-1095	502980, 502981, 502992, or 502997	9002	573806

DILL TPMS APPLICATIONS CHART ©

OE	Model	Model Year	Torque In-Lbs	Dill Kit #	Costco Service Pack #	Valve Stem Replacement	Costco Valve #	Dill Sensor	Costco Sensor #
Bugatti	Veyron	05-06	NA	1090K	502980	1092-1095	502980, 502981, 502992, or 502997	NA	N/A
Buick	Allure	07-08	80	1050K	502904	NO	NO	7001/HP	562515
Buick	Allure	09	---	VS950	502975	VS950	502975	7001R/HPR	562517
Buick	Enclave	08	80	1050K	502904	NO	NO	7001/HP	562515
Buick	Enclave	09-13	---	VS950	502975	VS950	502975	7001R/HPR	562517
Buick	Encore	13	---	VS950	502975	VS950	502975	7001R/HPR	562517
Buick	LaCrosse	07-08	80	1050K	502904	NO	NO	7001/HP	562515
Buick	LaCrosse	09-13	---	VS950	502975	VS950	502975	7001R/HPR	562517
Buick	Lesabre	07	---	VS950	502975	VS950	502975	7001R/HPR	562517
Buick	Lucerne	07-11	---	VS950	502975	VS950	502975	7001R/HPR	562517
Buick	Ranier	06-07	62	1070K	502911	NO	NO	7001/HP	562515
Buick	Ranier	07	---	VS950	502975	VS950	502975	7001R/HPR	562517
Buick	Regal	11-13	---	VS950	502975	VS950	502975	7001R/HPR	562517
Buick	Verano	12-13	---	VS950	502975	VS950	502975	7001R/HPR	562517
Cadillac	ATS	13-14	---	VS90		VS90		7001R/HPR	562517
Cadillac	ATS Sport	13	71	7020K	648487	VS70	707594	7001/HP	562515
Cadillac	CTS	04-07	62	1070K	502911	NO	NO	7001/HP	562515
Cadillac	CTS	08-13	---	VS950	502975	VS950	502975	7001R/HPR	562517
Cadillac	CTS-V	09-12	---	1050K	502904	NO	NO	7001/HP	562515
Cadillac	Deville	01-05	62	1080K	502913	NO	NO	9117	648485
Cadillac	DTS	06	80	1050K or 1070K	502904 OR 502911	NO	NO	7001/HP	562515
Cadillac	DTS	07-11	---	VS950	502975	VS950	502975	7001R/HPR	562517
Cadillac	Escalade-ESV-EXT	04	62	1070K	502911	NO	NO	20115	296740
Cadillac	Escalade-ESV-EXT	05-06	62	1070K	502911	NO	NO	20107	296738
Cadillac	Escalade-ESV-EXT	07	62	2020K	502931	NO	NO	7001/HP	562515
Cadillac	Escalade-ESV-EXT	07	80	1050K	502904	NO	NO	7001/HP	562515
Cadillac	Escalade-ESV-EXT	07-13	---	VS950	502975	VS950	502975	7001R/HPR	562517
Cadillac	Seville	01-04	62	1080K	502913	NO	NO	9117	648485
Cadillac	SRX	04-06	62	1070K	502911	NO	NO	7001/HP	562515
Cadillac	SRX	07-13	---	VS950	502975	VS950	502975	7001R/HPR	562517
Cadillac	STS	05-09	62	1070K	502911	NO	NO	7001/HP	562515
Cadillac	STS	09	80	1050K or 1070K	502904 OR 502911	NO	NO	7001/HP	562515
Cadillac	STS	09-11	---	VS950	502975	VS950	502975	7001R/HPR	562517
Cadillac	XLR	04-09	62	1070K	502911	NO	NO	7001/HP	562515
Cadillac	XTS	13	---	VS950	502975	VS950	502975	7001R/HPR	562517
**The 1050K is to be used on the Siemens sensors and the 1070K is to be used on the Schrader sensors.									
Chevrolet	Avalanche	04	62	1070K	502911	NO	NO	20115	296740
Chevrolet	Avalanche	05-06	62	1070K	502911	NO	NO	20107	296738
Chevrolet	Avalanche	07	62	2020K	502931	NO	NO	7001/HP	562515
Chevrolet	Avalanche	07	80	1050K	502904	NO	NO	7001/HP	562515
Chevrolet	Avalanche	07-13	---	VS950	502975	VS950	502975	7001R/HPR	562517
Chevrolet	Aveo	07-11	---	VS950	502975	VS950	502975	7001R/HPR	562517
Chevrolet	Camaro	10-13	---	VS950	502975	VS950	502975	7001R/HPR	562517
Chevrolet	Camaro Sport	12-13	62	7020K	648487	VS70	707594	7001/HP	562515
Chevrolet	Caprice	11-12	62	7020K	648487	VS70	707594	7001/HP	562515
Chevrolet	Captiva	12-13	---	VS950	502975	VS950	502975	7001R/HPR	562517
Chevrolet	Cobalt	08-10	80	1050K	502904	NO	NO	7001/HP	562515
Chevrolet	Cobalt	08-10	---	VS950	502975	VS950	502975	7001R/HPR	562517
Chevrolet	Colorado	07-12	62	1110K	502923	NO	NO	20131	296743
Chevrolet	Corvette	97-00	62	1077K	#N/A	NO	NO	28006	296754
Chevrolet	Corvette-C5-Z6	01-04	62	1080K	502913	NO	NO	9117	648485
Chevrolet	Corvette-C6	05-09	62	1070K	502911	NO	NO	7001/HP	562515
Chevrolet	Corvette	10-11	62	1070K	502911	NO	NO	7001/HP	562515
Chevrolet	Corvette	12-13	---	VS950	502975	VS950	502975	7001R/HPR	562517
Chevrolet	Cruze	11-13	---	VS950	502975	VS950	502975	7001R/HPR	562517
Chevrolet	Equinox	07-09	80	1050K	502904	NO	NO	7001/HP	562515
Chevrolet	Equinox	10-13	---	VS950	502975	VS950	502975	7001R/HPR	562517
Chevrolet	Express Series	08-09	80	1050K	502904	NO	NO	7001/HP	562515
Chevrolet	Express Series(1500)	10-13	---	VS950	502975	VS950	502975	7001R/HPR	562517
Chevrolet	Express Series(2500/3500)	10-13	---	VS950	502975	VS950	502975	7001R/HPR	562517
Chevrolet	G Series	08	80	1050K	502904	NO	NO	7001/HP	562515
Chevrolet	HHR	08-09	80	1050K or 1070K	502904 OR 502911	NO	NO	7001/HP	562515
Chevrolet	HHR	08-11	---	VS950	502975	VS950	502975	7001R/HPR	562517

DILL TPMS APPLICATIONS CHART ©

OE	Model	Model Year	Torque In-Lbs	Dill Kit #	Costco Service Pack #	Valve Stem Replacement	Costco Valve #	Dill Sensor	Costco Sensor #
Chevrolet	Impala	06-07	80	1050K or 1070K	502904 OR 502911	NO	NO	7001/HP	562515
Chevrolet	Impala	07-14	---	VS950	502975	VS950	502975	7001R/HPR	562517
Chevrolet	Malibu(< 10/14/07)	08	80	1050K	502904	NO	NO	7001/HP	562515
Chevrolet	Malibu	08-14	---	VS950	502975	VS950	502975	7001R/HPR	562517
Chevrolet	Monte Carlo	06-07	80	1050K or 1070K	502904 OR 502911	NO	NO	7001/HP	562515
Chevrolet	Monte Carlo	07	---	VS950	502975	VS950	502975	7001R/HPR	562517
Chevrolet	Silverado	04	62	1070K	502911	NO	NO	20115	296740
Chevrolet	Silverado	05-06	62	1070K	502911	NO	NO	20107	296738
Chevrolet	Silverado	07	62	2020K	502931	NO	NO	7001/HP	562515
Chevrolet	Silverado	07	80	1050K	502904	NO	NO	7001/HP	562515
Chevrolet	Silverado(1500)	07-14	---	VS950	502975	VS950	502975	7001R/HPR	562517
Chevrolet	Silverado(2500/3500)	07-14	---	VS950	502975	VS950	502975	7001R/HPR	562517
Chevrolet	Sonic	12-13	---	VS950	502975	VS950	502975	7001R/HPR	562517
Chevrolet	SSR	06-07	62	1070K	502911	NO	NO	7001/HP	562515
Chevrolet	Suburban	04	62	1070K	502911	NO	NO	20115	296740
Chevrolet	Suburban	05-06	62	1070K	502911	NO	NO	20107	296738
Chevrolet	Suburban	07	62	2020K	502931	NO	NO	7001/HP	562515
Chevrolet	Suburban	07	80	1050K	502904	NO	NO	7001/HP	562515
Chevrolet	Suburban(1500)	07-13	---	VS950	502975	VS950	502975	7001R/HPR	562517
Chevrolet	Suburban(2500)	07-13	---	VS950	502975	VS950	502975	7001R/HPR	562517
Chevrolet	Tahoe	04	62	1070K	502911	NO	NO	20115	296740
Chevrolet	Tahoe	05-06	62	1070K	502911	NO	NO	20107	296738
Chevrolet	Tahoe	07	62	2020K	502931	NO	NO	7001/HP	562515
Chevrolet	Tahoe	07	80	1050K	502904	NO	NO	7001/HP	562515
Chevrolet	Tahoe	07-13	---	VS950	502975	VS950	502975	7001R/HPR	562517
Chevrolet	Trailblazer	06-09	62	1070K	502911	NO	NO	7001/HP	562515
Chevrolet	Traverse	09-13	62	VS950	502975	VS950	502975	7001R/HPR	562517
Chevrolet	Uplander	08-09	80	2040K or 2000K	502971 OR 502927	NO	NO	7001/HP	562515
Chevrolet	Volt	10-13	---	VS950	502975	VS950	502975	7001R/HPR	562517
	**The 1050K is to be used on the Siemens sensors and the 1070K is to be used on the Schrader sensors.								
Chrysler	200	11-13	71	7020K	648487	VS70	707594	7001/HP	562515
Chrysler	300M(433 Mhz)	02-04	35	1080K	502913	NO	NO	7004	562516
Chrysler	300(315 Mhz)	05-07	71	1050K	502904	NO	NO	7001/HP	562515
Chrysler	300(433 Mhz)	08-10	71	1050K	502904	NO	NO	7004	562516
Chrysler	300(433 Mhz)	09-10	58	2030K	502970	9066K	648491	28214	296763
Chrysler	300(433 Mhz)	11-13	53	VS950	502975	VS950	502975	9398	574016
Chrysler	Aspen	07-09	71 or 58	1050K or 2030K	502904 OR 502970	9066K	648491	7001/HP	562515
Chrysler	Concorde(433 Mhz)	02-04	35	1080K	502913	NO	NO	7004	562516
Chrysler	Crossfire(433 Mhz)	04	35	1080K	502913	NO	NO	7004	562516
Chrysler	Crossfire	05	71 or 58	1050K or 2030K	502904 OR 502970	9066K	648491	7001/HP	562515
Chrysler	Crossfire(433 Mhz)	06-08	35	1080K	502913	NO	NO	7004	562516
Chrysler	Pacifica(433 Mhz)	04	35	1080K	502913	NO	NO	7004	562516
Chrysler	Pacifica	04-05	71	1050K	502904	NO	NO	7001/HP	562515
Chrysler	Pacifica	06-08	71	1050K	502904	NO	NO	7001/HP	562515
Chrysler	Prowler	01	35	1080K	502913	NO	NO	28004	296752
Chrysler	Prowler(433 Mhz)	02	35	1080K	502913	NO	NO	7004	562516
Chrysler	PT Cruiser	08-10	71	1050K	502904	NO	NO	7001/HP	562515
Chrysler	Sebring(315 Mhz)	07-10	71	1050K	502904	NO	NO	7001/HP	562515
Chrysler	Sebring(315 Mhz)	10	71	7020K	648487	VS70	707594	7001/HP	562515
Chrysler	Town & Country(433 Mhz)	02-03	35	1080K	502913	NO	NO	7004	562516
Chrysler	Town & Country	04-05	71	1050K	502904	NO	NO	7001/HP	562515
Chrysler	Town & Country	06-07	71	1050K	502904	NO	NO	7001/HP	562515
Chrysler	Town & Country (433 Mhz)	08-10	71	1050K	502904	NO	NO	7004	562516
Chrysler	Town & Country (433 Mhz)	10	71	7020K	648487	VS70	707594	7004	562516
Chrysler	Town & Country (433 Mhz)	11-13	---	VS950	502975	VS950	502975	9398	574016
Chrysler	Voyager(433 Mhz)	02-03	35	1080K	502913	NO	NO	7004	562516

DILL TPMS APPLICATIONS CHART ©

OE	Model	Model Year	Torque In-Lbs	Dill Kit #	Costco Service Pack #	Valve Stem Replacement	Costco Valve #	Dill Sensor	Costco Sensor #
	**The 1050K is to be used on the Siemens sensors and the 2030K is to be used on the Schrader sensors.								
Dodge	Avenger	08-10	71	1050K	502904	NO	NO	7001/HP	562515
Dodge	Avenger	10-13	71	7020K	648487	VS70	707594	7001/HP	562515
Dodge	Caliber	07-10	71	1050K	502904	NO	NO	7001/HP	562515
Dodge	Caliber	11-12	71	7020K	648487	VS70	707594	7001/HP	562515
Dodge	Caliber--export	12	71	7020K	648487	NO	NO	7004	562516
Dodge	Caravan(433 Mhz)	02-03	35	1080K	502913	NO	NO	7004	562516
Dodge	Caravan	04-05	71	1050K	502904	NO	NO	7001/HP	562515
Dodge	Caravan	06-07	71	1050K	502904	NO	NO	7001/HP	562515
Dodge	Challenger	08	71	1050K	502904	NO	NO	7004	562516
Dodge	Challenger--SRT (433 Mhz)	08-13	53	2030K	502970	9066K	648491	28214	296763
Dodge	Challenger(433 Mhz)	10-13	---	VS950	502975	VS950	502975	9398	574016
Dodge	Charger	06-07	71	1050K	502904	NO	NO	7001/HP	562515
Dodge	Charger(433 Mhz)	08	71	1050K	502904	NO	NO	7004	562516
Dodge	Charger(433 Mhz)	09-10	53	2030K	502970	9066K	648491	28291	467085
Dodge	Charger(433 Mhz)	10-13	---	VS950	502975	VS950	502975	9398	574016
Dodge	Dakota	08-10	53	2030K	502970	9066K	648491	7001/HP	562515
Dodge	Dakota	11	---	VS950	502975	VS950	502975	7001/HP	562515
Dodge	Dart	13		VS90		VS90		5775	
Dodge	Durango	07-09	71	1050K or 2030K	502904 OR 502970	NO	NO	7001/HP	562515
Dodge	Durango(433 Mhz)	11-13	---	VS950	502975	VS950	502975	9398	574016
Dodge	Grand Caravan(433 Mhz)	02-03	35	1080K	502913	NO	NO	7004	562516
Dodge	Grand Caravan	04-05	71	1050K	502904	NO	NO	7001/HP	562515
Dodge	Grand Caravan	06-07	71	1050K	502904	NO	NO	7001/HP	562515
Dodge	Grand Caravan (433 Mhz)	08-10	71	1050K	502904	NO	NO	7004	562516
Dodge	Grand Caravan (433 Mhz)	10	71	7020K	648487	NO	NO	7004	562516
Dodge	Grand Caravan(433 Mhz)	11-13	---	VS950	502975	VS950	502975	9398	574016
Dodge	Intrepid(433 Mhz)	02-04	35	1080K	502913	NO	NO	7004	562516
Dodge	Journey(433 Mhz)	09-10	71	1050K	502904	NO	NO	7004	562516
Dodge	Journey(433 Mhz)	10-11	71	7020K	648487	VS70	707594	7004	562516
Dodge	Journey(433 Mhz)	12	---	VS950	502975	VS950	502975	9398	574016
Dodge	Magnum	05-07	71	1050K	502904	NO	NO	7001/HP	562515
Dodge	Magnum(433 Mhz)	08	71	1050K	502904	NO	NO	7004	562516
Dodge	Nitro	07-11	71	1050K or 2030K	502904 OR 502970	NO	NO	7001/HP	562515
Dodge	Nitro(Alloy)	10-11	---	VS950	502975	VS950	502975	7001R/HPR	562517
Dodge	Ram(HP-315 Mhz) 1500/2500	08	53	2030K	502970	9066K	648491	7001/HP	562515
Dodge	Ram(433 Mhz) 1500	09	71	1050K	502904	NO	NO	7004	562516
Dodge	Ram(433 Mhz) 1500/2500	10-13	---	VS950	502975	VS950	502975	9398	574016
Dodge	Sprinter	07-12	54	1098K	503006	1098K	503006	1042	574595
Dodge	Stratus	07	71	1050K	502904	NO	NO	7001/HP	562515
Dodge	Viper(433 Mhz)	03-10	35	1080K	502913	NO	NO	7004	562516
	**The 1050K is to be used on the Siemens sensors and the 2030K is to be used on the Schrader sensors.								
Ferrari	430(433 Mhz)	06-07	---	1090K	502980	1092	502980	9001	545608
Ferrari	430(433 Mhz)	08-14	---	1090K	502980	1092	502980	9007	571724
Ferrari	458(433 Mhz)	10-14	---	1090K	502980	1092	502980	9008	574587
Ferrari	550(433 Mhz)	02-14	---	1090K	502980	1092	502980	9001	545608
Ferrari	575(433 Mhz)	02-06	---	1090K	502980	1092	502980	9001	545608
Ferrari	575(315 Mhz)	02-05	---	1090K	502980	1092	502980	9004	489773
Ferrari	599	04-14		1090K	502980	1092	502980	9001	545608
Ferrari	612(433 Mhz)	04-11	---	1090K	502980	1092	502980	9001	545608
Ferrari	California(433 Mhz)	10-14	---	1090K	502980	1092	502980	9008	574587
Ferrari	Enzo(433 Mhz)	03-04	---	1090K	502980	1092	502980	9005	574094
Ferrari	FX(433 Mhz)	05-06	---	1090K	502980	1092	502980	9005	574094
Ferrari	Scaglietti	05-14	---	1090K	502980	1092	502980	9001	545608
Ferrari	Spider(433 Mhz)	02-09	---	1090K	502980	1092	502980	9001	545608
Fiat	500(433 Mhz)	11-13	---	VS950	502975	VS950	502975	9398	574016

DILL TPMS APPLICATIONS CHART ©

OE	Model	Model Year	Torque In-Lbs	Dill Kit #	Costco Service Pack #	Valve Stem Replacement	Costco Valve #	Dill Sensor	Costco Sensor #
Ford	Crown Victoria	06-11	---	1194	1194 Band	NO	NO	7001/HP	562515
Ford	C-Max	12-13	---	VS950	502975	VS950	502975	7001R/HPR	562517
Ford	E Series	07-09	---	1194	1194 Band	NO	NO	1048-HP	518228
Ford	E Series(HP)	10-13	---	VS950	502975	VS950	502975	7001R/HPR	562517
Ford	Edge	07-10	---	1194	1194 Band	NO	NO	7001/HP	562515
Ford	Edge	11-13	---	VS950	502975	VS950	502975	7001R/HPR	562517
Ford	Escape	06-08	---	1194	1194 Band	NO	NO	7001/HP	562515
Ford	Escape	09-13	---	VS950	502975	VS950	502975	7001R/HPR	562517
Ford	Expedition(433 Mhz)	03-04	44	1060K	502905	NO	NO	7004	562516
Ford	Expedition(315 Mhz)	05-06	44	1060K	502905	NO	NO	7001/HP	562515
Ford	Expedition	07-10	---	1194	1194 Band	NO	NO	7001/HP	562515
Ford	Expedition	11-13	---	VS950	502975	VS950	502975	7001R/HPR	562517
Ford	Explorer(433 Mhz)	02-05	44	1060K	502905	NO	NO	7004	562516
Ford	Explorer	06-10	---	1194	1194 Band	NO	NO	7001/HP	562515
Ford	Explorer	11-13	---	VS950	502975	VS950	502975	7001R/HPR	562517
Ford	Explorer Sport Trac	07-10	---	1194	1194 Band	NO	NO	7001/HP	562515
Ford	F 150	07-08	---	1194	1194 Band	NO	NO	7001/HP	562515
Ford	F 150	09-13	---	VS950	502975	VS950	502975	7001R/HPR	562517
Ford	F 150 (433 MHz)	13	62	7020K	648487	VS70	707594	7004	562516
Ford	Fiesta	11-13	---	VS950	502975	VS950	502975	7001R/HPR	562517
Ford	500	08-09	---	1194	1194 Band	NO	NO	7001/HP	562515
Ford	Flex	09-10	---	1194	1194 Band	NO	NO	7001/HP	562515
Ford	Flex	11-13	---	VS950	502975	VS950	502975	7001R/HPR	562517
Ford	Focus	07-09	---	1194	1194 Band	NO	NO	7001/HP	562515
Ford	Focus	10-13	---	VS950	502975	VS950	502975	7001R/HPR	562517
Ford	Freestar(315 Mhz)	04-05	44	1060K	502905	NO	NO	7001/HP	562515
Ford	Freestar	06-07	---	1194	1194 Band	NO	NO	7001/HP	562515
Ford	Fusion	07-09	---	1194	1194 Band	NO	NO	7001/HP	562515
Ford	Fusion	10-13	---	VS950	502975	VS950	502975	7001R/HPR	562517
Ford	Mustang	07-09	---	1194	1194 Band	NO	NO	7001/HP	562515
Ford	Mustang	10-13	---	VS950	502975	VS950	502975	7001R/HPR	562517
Ford	Ranger	07-11	---	1194	1194 Band	NO	NO	7001/HP	562515
Ford	Ranger	12	---	VS950	502975	VS950	502975	7001R/HPR	562517
Ford	Shelby GT	13	---	VS950	502975	VS950	502975	7001R/HPR	562517
Ford	Super Duty (250/350/450) Pre-June 2009	07-10	---	1194	1194 Band	NO	NO	1048HP	518228
Ford	Super Duty (250/350/450) Post-June 2009	10-13	---	VS950	502975	VS950	502975	7001R/HPR	562517
Ford	Taurus(Pre-May 2010)	08-10	---	1194	1194 Band	NO	NO	7001/HP	562515
Ford	Taurus(Post-May 2010)	11-13	---	VS950	502975	VS950	502975	7001R/HPR	562517
Ford	Taurus X	08-09	---	1194	1194 Band	NO	NO	7001/HP	562515
Ford	Transit	10-13	---	VS950	502975	VS950	502975	7001R/HPR	562517
*Redi-Sensor relearn must be performed with scan tool and not magnet.									
GMC	Acadia	07-08	80	1050K	502904	NO	NO	7001/HP	562515
GMC	Acadia	09-13	---	VS950	502975	VS950	502975	7001R/HPR	562517
GMC	Canyon	07-12	62	1110K	502923	NO	NO	20131	296743
GMC	Envoy	05-07	62	1070K	502911	NO	NO	7001/HP	562515
GMC	Envoy	07-09	---	VS950	502975	VS950	502975	7001R/HPR	562517
GMC	Savana	08-09	80	1050K	502904	NO	NO	7001/HP	562515
GMC	Savana(1500)	10-13	---	VS950	502975	VS950	502975	7001R/HPR	562517
GMC	Savana(2500/3500)	10-13	---	VS950	502975	VS950	502975	7001R/HPR	562517
GMC	Sierra	04	62	1070K	502911	NO	NO	20115	296740
GMC	Sierra	05-06	62	1070K	502911	NO	NO	20107	296738
GMC	Sierra	07	62	2020K	502931	NO	NO	7001/HP	562515
GMC	Sierra	07	80	1050K	502904	NO	NO	7001/HP	562515
GMC	Sierra(1500)	07-14	---	VS950	502975	VS950	502975	7001R/HPR	562517
GMC	Sierra(2500/3500)	07-14	---	VS950	502975	VS950	502975	7001R/HPR	562517
GMC	Terrain	10-13	---	VS950	502975	VS950	502975	7001R/HPR	562517
GMC	Yukon	04	62	1070K	502911	NO	NO	20115	296740
GMC	Yukon	05-06	62	1070K	502911	NO	NO	20107	296738
GMC	Yukon	07	62	2020K	502931	NO	NO	7001/HP	562515
GMC	Yukon	07	80	1050K	502904	NO	NO	7001/HP	562515
GMC	Yukon(1500)	07-13	---	VS950	502975	VS950	502975	7001R/HPR	562517
GMC	Yukon(2500)	07-13	---	VS950	502975	VS950	502975	7001R/HPR	562517
Honda	Accord	08-12	35	1100K	502921	NO	NO	7002	707597
Honda	Civic	08-11	35	2040K	502971	NO	NO	7002	707597
Honda	Civic	12-13	35	2040K	502971	NO	NO	7002	707597
Honda	CR-V	07-11	35	1100K	502921	NO	NO	7002	707597
Honda	CR-Z	11-13	35	2040K	502971	NO	NO	7002	707597

DILL TPMS APPLICATIONS CHART ©

OE	Model	Model Year	Torque In-Lbs	Dill Kit #	Costco Service Pack #	Valve Stem Replacement	Costco Valve #	Dill Sensor	Costco Sensor #
Honda	Crosstour	10-13	71	7020K	648487	VS70	707594	7002	707597
Honda	Element	06-07	35	1096	300415	1096	300415	7002	707597
Honda	Element	08	35	2040K or 2000K	502971 OR 502927	NO OR 1096	NO OR 300415	7002	707597
Honda	Element	09-11	35	2040K	502971	NO	NO	7002	707597
Honda	Fit	08	35	1100K	502921	NO	NO	7002	707597
Honda	Fit	09-13	35	2040K	502971	NO	NO	7002	707597
Honda	Insight	10-13	35	2040K	502971	1096	300415	7002	707597
Honda	Odyssey EX, EX-L, LX	06-07	35	1096	300415	1096	300415	7002	707597
Honda	Odyssey EX, EX-L, LX	08-10	35	2040K or 2000K	502971 OR 502927	NO OR 1096	NO OR 300415	7002	707597
Honda	Odyssey EX, EX-L, LX	11-13	35	2040K	502971	NO	NO	7002	707597
Honda	Odyssey Touring	05-07	35	1096	300415	1096	300415	1057	503013
Honda	Odyssey Touring	08-10	35	2040K or 2000K	502971 OR 502927	NO OR 1096	NO OR 300415	1057	503013
Honda	Odyssey Touring	11-12	35	2040K	502971	NO	NO	7002	707597
Honda	Pilot(Steel)-2.25"	05	35	1097	300414	1097	300414	1059	518211
Honda	Pilot-1.75"	05-08	35	1096	300415	1096	300415	1057	503013
Honda	Pilot	09-13	35	1100K	502921	NO	NO	1209	574590
Honda	Pilot(Steel)	09-13	35	1100K	502921	NO	NO	1219	N/A
Honda	Ridgeline(RT)-2.25"	06-08	35	1097	300414	1097	300414	1059	518211
Honda	Ridgeline-1.75"	06-12	35	1096	300415	1096	300415	1057	503013
Honda	Ridgeline(Alloy)	09-13	35	2040K or 2000K	502971 OR 502927	NO OR 1096	NO OR 300415	1057	503013
Honda	S2000	08-09	35	1100K	502921	NO	NO	7002	707597
Hummer	H2	08-09	---	VS950	502975	VS950	502975	7001R/HPR	562517
Hummer	H3	06-10	62	1110K	502923	NO	NO	20131	296743
Hummer	H3T	09-10	62	1110K	502923	NO	NO	20131	296743
Hyundai	Accent(Lo-Line)	08-11	31-40	2040K	502971	NO	NO	7002	707597
Hyundai	Accent	12-13	71	7020K	648487	VS70	707594	7001/HP	562515
Hyundai	Azera	07-12	31-40	1096	300415	1096	300415	7002	707597
Hyundai	Elantra	07-10	31-40	1096	300415	1096	300415	7002	707597
Hyundai	Elantra(Post Nov)	11-13	31-40	2040K	502971	VS965	707626	7002	707597
Hyundai	Elantra(Touring)	09-12	71	1050K or 7020K	648487	VS70	707594	7001/HP	562515
Hyundai	Elantra GT	13	71	7020K	648487	VS70	707594	7001/HP	562515
Hyundai	Entourage	07-09	31-40	1096	300415	1096	300415	1028	518217
Hyundai	Equus(Hi-Line)	11-13	31-40	2040K	502971	NO	NO	1029	648483
Hyundai	Genesis(Hi-line)	09-13	31-40	2040K	502971	NO	NO	1029	648483
Hyundai	Genesis Coupe	10-13	71	7020K	648487	VS70	707594	7001/HP	562515
Hyundai	Santa Fe (Thru July 2007)	07-08	31-40	1096	300415	1096	300415	1028	518217
Hyundai	Santa Fe (Thru Sept 2009)	08-10	31-40	1096	300415	1096	300415	7002	707597
Hyundai	Santa Fe	10-12	11	VS1010	502976	VS1010	502976	7002	707597
Hyundai	Santa Fe Turbo	13	71	7020K	648487	VS70	707594	7001/HP	562515
Hyundai	Sonata	07-08	31-40	1096	300415	1096	300415	1058	518214
Hyundai	Sonata(Lo-Line) --Late '08 Builds	08-10	31-40	2040K	502971	NO	NO	7002	707597
Hyundai	Sonata	11-13	71	7020K	648487	VS70	707594	7001/HP	562515
Hyundai	Tiburon	07-08	31-40	1096	300415	1096	300415	7002	707597
Hyundai	Tucson	07-10	31-40	1096	300415	1096	300415	7002	707597
Hyundai	Tucson	10-13	31-40	2040K	502971	NO	NO	7002	707597
Hyundai	Velostar	12-13	---	VS950	502975	VS950	502975	NEW	N/A
Hyundai	Veracruz	07-08	31-40	1096	300415	1096	300415	1028	518217
Hyundai	Veracruz	08-12	31-40	1096	300415	1096	300415	7002	707597
Infiniti	EX35	08-10	35	1100K	502921	NO	NO	7001/HP	562515
Infiniti	EX35	11-12	35	1100K	502921	NO	NO	1216	643321
Infiniti	EX37	13	35	1100K	502921	NO	NO	1216	643321
Infiniti	FX35(Pre-June)	03-08	45-60	1080K	502913	NO	NO	7001/HP	562515
Infiniti	FX35(Post-June)	09-10	35	1100K	502921	NO	NO	7001/HP	562515
Infiniti	FX35	11	35	1100K	502921	NO	NO	1216	643321
Infiniti	FX37	13	35	1100K	502921	NO	NO	1216	643321
Infiniti	FX45(Pre-June)	03-07	45-60	1080K	502913	NO	NO	7001/HP	562515
Infiniti	FX45(Post-June)	07-08	66	2030K	502970	NO	NO	7001/HP	562515
Infiniti	FX50	09-10	66	1100K	502921	NO	NO	7001/HP	562515
Infiniti	FX50	11-13	66	1100K	502921	NO	NO	1216	643321
Infiniti	G25	11-12	66	1100K	502921	NO	NO	1216	643321
Infiniti	G35	03-06	45-60	1080K	502913	NO	NO	7001/HP	562515
Infiniti	G35(Sedan)	07-08	66	1100K	502921	NO	NO	7001/HP	562515

DILL TPMS APPLICATIONS CHART ©

OE	Model	Model Year	Torque In-Lbs	Dill Kit #	Costco Service Pack #	Valve Stem Replacement	Costco Valve #	Dill Sensor	Costco Sensor #
Infiniti	G35(Coupe)	08	66	2030K	502970	NO	NO	7001/HP	562515
Infiniti	G37	08-10	66	1100K	502921	NO	NO	7001/HP	562515
Infiniti	G37	11-13	66	1100K	502921	NO	NO	1216	643321
Infiniti	JX35	13	71	7020K	648487	VS70	707594	5556	
Infiniti	M35	06-07	45-60	1080K	502913	NO	NO	7001/HP	562515
Infiniti	M35	08-10	66	2030K	502970	NO	NO	7001/HP	562515
Infiniti	M35h	13	66	1100K	502921	NO	NO	1216	643321
Infiniti	M37	11-13	66	1100K	502921	NO	NO	1216	643321
Infiniti	M45	03-07	45-60	1080K	502913	NO	NO	7001/HP	562515
Infiniti	M45	08-10	66	2030K	502970	NO	NO	7001/HP	562515
Infiniti	M56	11-13	66	1100K	502921	NO	NO	1216	643321
Infiniti	Q45(pre-July)	03-06	45-60	1080K	502913	NO	NO	7001/HP	562515
Infiniti	Q45(Post-Aug)	06	66	2030K	502970	NO	NO	7001/HP	562515
Infiniti	QX4	03	45-60	1080K	502913	NO	NO	7001/HP	562515
Infiniti	QX56(Steel)	05-06	49	1130K	502926	NO	NO	7001/HP	562515
Infiniti	QX56(Alloy)	04-07	49	1080K	502913	NO	NO	7001/HP	562515
Infiniti	QX56(Post-April)	07-10	66	2030K	502970	NO	NO	7001/HP	562515
Infiniti	QX56	11-13	66	1100K	502921	NO	NO	1216	643321
Isuzu	Ascender	06-08	62	1070K	502911	NO	NO	7001/HP	562515
Isuzu	I-290	07-08	62	1110K	502923	NO	NO	20131	296743
Isuzu	I-370	07-08	62	1110K	502923	NO	NO	20131	296743
Isuzu	Rodeo(433 Mhz)	04	35	1080K	502913	NO	NO	7004	562516
Jaguar	S(315 Mhz)	05-08	71	1050K	502904	NO	NO	1055	503011
Jaguar	S(433 Mhz)	05-08	71	1050K	502904	NO	NO	1046	574421
Jaguar	XF(315 Mhz)	09-10	71	1050K	502904	NO	NO	1055	503011
Jaguar	XF(315 Mhz)	10-13	71	7020K	648487	VS70	707594	1055	503011
Jaguar	XF(433 Mhz)	09-10	71	1050K	502904	NO	NO	1046	574421
Jaguar	XF(433 Mhz)	10-11	71	7020K	648487	NO	NO	1046	574421
Jaguar	XJ(315 Mhz)	04-10	71	1050k	502904	NO	NO	1055	503011
Jaguar	XJ(315 Mhz)	10-11	71	7020K	648487	VS70	707594	1055	503011
Jaguar	XJ(315 Mhz)	12-13	71	1050K	502904	NO	NO	1045	N/A
Jaguar	XJ(433 Mhz)	04-10	71	1050K	502904	NO	NO	1046	574421
Jaguar	XJ(433 Mhz)	10-11	71	7020K	648487	NO	NO	1046	574421
Jaguar	XK(315 Mhz)	05-10	71	7020K	648487	NO	NO	1055	503011
Jaguar	XK(315 Mhz)	10-13	71	7020K	648487	VS70	707594	1055	503011
Jaguar	XK(433 Mhz)	07-10	71	1050K	502904	NO	NO	1046	574421
Jaguar	XK(433 Mhz)	10-12	71	7020K	648487	NO	NO	1046	574421
Jeep	Commander	06	71	1050K	502904	NO	NO	7001/HP	562515
Jeep	Commander	07	58	2030K	502970	9066K	648491	7001/HP	562515
Jeep	Commander (433 Mhz)	08-10	58	2030K	502970	9066K	648491	7004	562516
Jeep	Compass	07-09	71	1050K	502904	NO	NO	7001/HP	562515
Jeep	Compass	10-13	71 or 58	7020K or 2030K	648487	9066K	648491	7001/HP	562515
Jeep	Compass	14		VS950	502975	VS950	502975	7001R/HPR	562517
Jeep	Grand Cherokee(433 Mhz)	02-04	64	1080K	502913	NO	NO	7004	562516
Jeep	Grand Cherokee	05-06	71	1050K	502904	NO	NO	7001/HP	562515
Jeep	Grand Cherokee	07	58	2030K	502970	9066K	648491	7001/HP	562515
Jeep	Grand Cherokee (433 Mhz)	08-10	58	2030K	502970	9066K	648491	7004	562516
Jeep	Grand Cherokee(433 Mhz)	11-14	---	VS950	502975	VS950	502975	9398	574016
Jeep	Grand Cherokee SRT	12-14	53	2030K	502970	9066K	648491	28214	296763
Jeep	Liberty(433 Mhz)	04	64	1080K	502913	NO	NO	7004	562516
Jeep	Liberty	05-08	71	1050K	502904	NO	NO	7001/HP	562515
Jeep	Liberty	07-09	58	2030K	502970	9066K	648491	7001/HP	562515
Jeep	Liberty(433 Mhz)--Non Sport	09	58	2030K	502970	9066K	648491	7004	562516
Jeep	Liberty	10	58	2030K	502970	9066K	648491	7001/HP	562515
Jeep	Liberty	10-11	---	VS950	502975	VS950	502975	7001R/HPR	562517
Jeep	Liberty(433 Mhz)	12	---	VS950	502975	VS950	502975	9481	N/A

DILL TPMS APPLICATIONS CHART ©

OE	Model	Model Year	Torque In-Lbs	Dill Kit #	Costco Service Pack #	Valve Stem Replacement	Costco Valve #	Dill Sensor	Costco Sensor #
Jeep	Patriot	07-10	71	1050K	502904	NO	NO	7001/HP	562515
Jeep	Patriot	10-13	58	2030K	502970	9066K	648491	7001/HP	562515
Jeep	Wrangler(Alloy)	07-08	58	2030K	502970	9066K	648491	7001/HP	562515
Jeep	Wrangler	09-10	58	2030K	502970	9066K	648491	7004	562516
Jeep	Wrangler	10-11	---	VS950	502975	VS950	502975	7001R/HPR	562517
Jeep	Wrangler 433 Mhz	12-13	---	VS950	502975	VS950	502975	9398	574016
Jeep	Wrangler Export(433 Mhz)	11-12	---	VS950	502975	VS950	502975	9481	N/A
**The 1050K is to be used on the Siemens sensors and the 2030K is to be used on the Schrader sensors.									
KIA	Amanti	07-09	31-40	1096	300415	1096	300415	1057	503013
KIA	Borrego(Lo-Line)	09	31-40	2040K	502971	NO	NO	7002	707597
KIA	Cadenza	14	60	7020K	648487	VS70	707594	7001/HP	562515
KIA	Forte	10-13	71	7020K	648487	VS70	707594	7001/HP	562515
KIA	Magentis	08-10	31-40	1096	300415	1096	300415	7002	707597
KIA	Mohave	09	31-40	2040K	502971	NO	NO	7002	707597
KIA	Optima(Lo-Line)	06-10	31-40	1096	300415	1096	300415	7002	707597
KIA	Optima	11-13	71	7020K	648487	VS70	707594	7001/HP	562515
KIA	Rio-5(Lo-Line)	08-11	31-40	2040K	502971	NO	NO	7002	707597
KIA	Rio 5(Lo-Line)	12-13	31-40	2040K	502971	VS965	707626	NEW	N/A
KIA	Rondo(Lo-Line)	07-09	31-40	1096	300415	1096	300415	7002	707597
KIA	Sedona(Hi-Line)	06-08	31-40	1096	300415	1096	300415	1028	518217
KIA	Sedona(Lo-Line)	09-12	31-40	1096	300415	1096	300415	7002	707597
KIA	Sorento	05-09	31-40	1096	300415	1096	300415	1057	503013
KIA	Sorento	09	31-40	1096	300415	1096	300415	7002	707597
KIA	Sorento	11-14	71	7020K	648487	VS70	707594	7001/HP	562515
KIA	Soul	10-13	71	7020K	648487	VS70	707594	7001/HP	562515
KIA	Spectra-5(Lo-Line)	07-09	31-40	2040K	502971	NO	NO	7002	707597
KIA	Sportage	06-08	31-40	1096	300415	1096	300415	7002	707597
KIA	Sportage(Lo-Line)	09-13	31-40	2040K	502971	NO	NO	7002	707597
KIA	Tuscany	07-08	31-40	1096	300415	1096	300415	7002	707597
Land Rover	LR2(315 Mhz)	08-10	71	1050K	502904	NO	NO	1045	N/A
Land Rover	LR2(315 Mhz)	11-13	71	1050K	502904	NO	NO	1045	N/A
Land Rover	LR2(433 Mhz)	10-11	71	7020K	648487	VS70	707594	1046	574421
Land Rover	LR3(433 Mhz)	02-05	58	1090K	502980	1092-1095	502980, 502981, 502992, or	9003	661042
Land Rover	LR3(315 Mhz)	06-09	71	1050K	502904	NO	NO	1055	503011
Land Rover	LR3(433 Mhz)	06-09	71	1050K	502904	NO	NO	1046	574421
Land Rover	LR4(315 Mhz)	10-13	71	1050K	502904	NO	NO	1045	N/A
Land Rover	LR4(433 Mhz)	10-11	71	7020K	648487	NO	NO	1046	574421
Land Rover	Range Rover (315 Mhz)	06-09	71	1050K	502904	NO	NO	1055	503011
Land Rover	Range Rover (315 Mhz)	10-13	71	1050K	502904	NO	NO	1045	N/A
Land Rover	Range Rover (433 Mhz)	06-09	71	1050K	502904	NO	NO	1046	574421
Land Rover	Range Rover (433 Mhz)	10-11	71	7020K	648487	NO	NO	1046	574421
Land Rover	Range Rover Sport(315 Mhz)	06-09	71	1050K	502904	NO	NO	1055	503011
Land Rover	Range Rover Sport(315 Mhz)	10-13	71	1050K	502904	NO	NO	1045	N/A
Land Rover	Range Rover Sport(433 Mhz)	06-09	71	1050K	502904	NO	NO	1046	574421
Land Rover	Range Rover Sport(433 Mhz)	10-11	71	7020K	648487	NO	NO	1046	574421
Lexus	CT	11-13	35	1100K	502921	NO	NO	7002	707597
Lexus	ES	07-12	35	1100K	502921	NO	NO	7002	707597
Lexus	ES	13	35	1100K	502921	NO	NO	1218	643351
Lexus	GS	05-11	35	1100K	502921	NO	NO	7002	707597
Lexus	GS	13	35	1100K	502921	NO	NO	1218	643351
Lexus	GX470	04-06	35	1110K	502923	NO	NO	7002	707597
Lexus	GX	07-13	35	1100K	502921	NO	NO	7002	707597

DILL TPMS APPLICATIONS CHART ©

OE	Model	Model Year	Torque In-Lbs	Dill Kit #	Costco Service Pack #	Valve Stem Replacement	Costco Valve #	Dill Sensor	Costco Sensor #
Lexus	HS Series	10-12	35	1100K	502921	NO	NO	7002	707597
Lexus	IS Series	06-13	35	1100K	502921	NO	NO	7002	707597
Lexus	LFA	12-13	35	1100K	502921	NO	NO	7002	707597
Lexus	LS	07-12	35	1100K	502921	NO	NO	7002	707597
Lexus	LS	13	35	1100K	502921	NO	NO	1218	643351
Lexus	LX	05-13	35	1100K	502921	NO	NO	7002	707597
Lexus	RX	06-13	35	1100K	502921	NO	NO	7002	707597
Lexus	SC430 White ID	02-06	27	1120K	502924	NO	NO	1217-WH	432483
Lexus	SC430 Blue ID	02-06	27	1120K	502924	NO	NO	1217-BL	432484
Lexus	SC430 Red ID	02-06	27	1120K	502924	NO	NO	1217-RD	432486
Lexus	SC430 Gold ID	02-06	27	1120K	502924	NO	NO	1217-YL	432487
Lexus	SC	07-10	35	1100K	502921	NO	NO	7002	707597
Lincoln	Aviator(433 Mhz)	03-05	44	1060K	502905	NO	NO	7004	562516
Lincoln	Mark LT	07-08	---	1194	1194 Band	NO	NO	7001/HP	562515
Lincoln	MKS	09-10	---	1194	1194 Band	NO	NO	7001/HP	562515
Lincoln	MKS	11-13	---	VS950	502975	VS950	502975	7001R/HPR	562517
Lincoln	MKT	10	---	1194	1194 Band	NO	NO	7001/HP	562515
Lincoln	MKT	11-13	---	VS950	502975	VS950	502975	7001R/HPR	562517
Lincoln	MKX	07-10	---	1194	1194 Band	NO	NO	7001/HP	562515
Lincoln	MKX	11-13	---	VS950	502975	VS950	502975	7001R/HPR	562517
Lincoln	MKZ	07-09	---	1194	1194 Band	NO	NO	7001/HP	562515
Lincoln	MKZ	10-13	---	VS950	502975	VS950	502975	7001R/HPR	562517
Lincoln	Navigator(433 Mhz)	03-04	44	1060K	502905	NO	NO	7004	562516
Lincoln	Navigator(315 Mhz)	05-06	44	1060K	502905	NO	NO	7001/HP	562515
Lincoln	Navigator	07-10	---	1194	1194 Band	NO	NO	7001/HP	562515
Lincoln	Navigator	11-13	---	VS950	502975	VS950	502975	7001R/HPR	562517
Lincoln	Town Car	06-11	---	1194	1194 Band	NO	NO	7001/HP	562515
*Redi-Sensor relearn must be performed with scan tool and not magnet.									
Maserati	Quattroporte-- Thru December	04-09	35	1090K	502980	1092	502980	9001	545608
Maserati	Quattroporte-- Post January	10-14	35	1090K	502980	1092	502980	9008	574587
Maserati	Coupe-- Thru June	09	35	1090K	502980	1092	502980	9001	545608
Maserati	Coupe-- Post July	09-14	35	1090K	502980	1092	502980	9008	574587
Mazda	B Series	07-09	---	1194	1194 Band	NO	NO	7001/HP	562515
Mazda	2	11-13	71	7020K	648487	VS70	707594	7001/HP	562515
Mazda	3	04	71	1194	1194 Band	NO	NO	7001/HP	562515
Mazda	3	05-09	71	1050K	502904	NO	NO	7001/HP	562515
Mazda	3	10-13	71	7020K	648487	VS70	707594	7001/HP	562515
Mazda	5	06-09	71	1050K	502904	NO	NO	7001/HP	562515
Mazda	5	10-12	71	7020K	648487	VS70	707594	7001/HP	562515
Mazda	6	05-10	71	1050K	502904	NO	NO	7001/HP	562515
Mazda	6	10-13	71	7020K	648487	VS70	707594	7001/HP	562515
Mazda	CX-7	07-09	71	1050K	502904	NO	NO	7001/HP	562515
Mazda	CX-7	10-12	71	7020K	648487	VS70	707594	7001/HP	562515
Mazda	CX-9	07-09	71	1050K	502904	NO	NO	7001/HP	562515
Mazda	CX-9	10-12	71	7020K	648487	VS70	707594	7001/HP	562515
Mazda	MX-5 Miata	06-09	71	1050K	502904	NO	NO	7001/HP	562515
Mazda	MX-5 Miata	10-13	71	7020K	648487	VS70	707594	7001/HP	562515
Mazda	RX-8	04	71	1194	1194 Band	NO	NO	7001/HP	562515
Mazda	RX-8	05-09	71	1050K	502904	NO	NO	7001/HP	562515
Mazda	RX-8	10-11	71	7020K	648487	VS70	707594	7001/HP	562515
Mazda	Speed 3	10-12	71	7020K	648487	VS70	707594	7001/HP	562515
Mazda	Speed 6	07-08	71	1050K	502904	NO	NO	7001/HP	562515
Mazda	Tribute	06-08	---	1194	1194 Band	NO	NO	7001/HP	562515
Mazda	Tribute	09-11	---	VS950	502975	VS950	502975	7001R/HPR	562517

DILL TPMS APPLICATIONS CHART ©

OE	Model	Model Year	Torque In-Lbs	Dill Kit #	Costco Service Pack #	Valve Stem Replacement	Costco Valve #	Dill Sensor	Costco Sensor #
M-Benz	C Class(433 Mhz)	07-13	53	2030K	502970	9066K	648491	28214	296763
M-Benz	CL Class(315 Mhz)	00-06	35	1090K	502980	1094	502992	9004	489773
M-Benz	CL Class(433 Mhz)	00-06	35	1090K	502980	1094	502992	9001	545608
M-Benz	CL Class(433 Mhz)	09-13	53	2030K	502970	9066K	648491	28214	296763
M-Benz	CL 63-65-550-600 (315 Mhz)	07-11	53	1040K	502977	1040K	502977	1054	503010
M-Benz	CL 63-65-550-600 (433 Mhz)	07-11	53	1040K	502977	1040K	502977	1049	574586
M-Benz	CLKClass(315 Mhz)	06-07	35	1090K	502980	1094	502992	9004	489773
M-Benz	CLK Class(433 Mhz)	08-09	53	2030K	502970	9066K	648491	28214	296763
M-Benz	CLS 55-63-500-550 (315 Mhz)	06-11	53	1040K	502977	1040K	502977	1054	503010
M-Benz	CLS 55-63-500-550 (433 Mhz)	06-09	53	1040K	502977	1040K	502977	1049	574586
M-Benz	CLS Class(433 Mhz)	08-13	53	2030K	502970	9066K	648491	28214	296763
M-Benz	CLS Class(433 Mhz)	11	53	1040K	502977	1040K	502977	1049	574586
M-Benz	E Class(315 Mhz)	00-05	35	1090K	502980	1094	502992	9004	489773
M-Benz	E Class(433 Mhz)	00-05	35	1090K	502980	1094	502992	9001	545608
M-Benz	E Class(315 Mhz)	06-10	53	1040K	502977	1040K	502977	1054	503010
M-Benz	E Class(433 Mhz)	06-10	53	1040K	502977	1040K	502977	1049	574586
M-Benz	E Class(433 Mhz)	10-13	53	2030K	502970	9066K	648491	28214	296763
M-Benz	G Class(433 Mhz)	07-13	53	2030K	502970	9066K	648491	28214	296763
M-Benz	GL Class(315 Mhz)	07-09	53	1040K	502977	1040K	502977	1054	503010
M-Benz	GL Class(433 Mhz)	07-09	53	1040K	502977	1040K	502977	1049	574586
M-Benz	GL(433 Mhz)	10-13	53	2030K	502970	9066K	648491	28214	296763
M-Benz	GLK(433 Mhz)	10-13	53	2030K	502970	9066K	648491	28214	296763
M-Benz	ML Class(315 Mhz)	06-10	53	1040K	502977	1040K	502977	1054	503010
M-Benz	ML Class(433 Mhz)	06-10	53	1040K	502977	1040K	502977	1049	574586
M-Benz	ML Class(433 Mhz)	10-13	53	2030K	502970	9066K	648491	28214	296763
M-Benz	R Class(315 Mhz)	06-09	53	1040K	502977	1040K	502977	1054	503010
M-Benz	R Class(433 Mhz)	06-09	53	1040K	502977	1040K	502977	1049	574586
M-Benz	R Class(433 Mhz)	10	35	2030K	502970	9066K	648491	28214	296763
M-Benz	R Class(433 Mhz)	11	53	1040K	502977	1040K	502977	1049	574586
M-Benz	S Class(315 Mhz)	00-06	35	1090K	502980	1094	502992	9004	489773
M-Benz	S Class(433 Mhz)	00-06	35	1090K	502980	1094	502992	9001	545608
M-Benz	S Class(315 Mhz)	07-11	53	1040K	502977	1040K	502977	1054	503010
M-Benz	S Class(433 Mhz)	07-10	53	1040K	502977	1040K	502977	1049	574586
M-Benz	S(433 Mhz)	10-11	53	2030K	502970	9066K	648491	28214	296763
M-Benz	SL Class(315 Mhz)	00-05	35	1090K	502980	1094	502992	9004	489773
M-Benz	SL Class(433 Mhz)	00-05	35	1090K	502980	1094	502992	9001	545608
M-Benz	SL Class(315 Mhz)	06-12	53	1040K	502977	1040K	502977	1054	503010
M-Benz	SL Class(433 Mhz)	06-09	53	1040K	502977	1040K	502977	1049	574586
M-Benz	SL Class(433 Mhz)	13	53	2030K	502970	9066K	648491	28214	296763
M-Benz	SLK Class(433 Mhz)	08-13	53	2030K	502970	9066K	648491	28214	296763
M-Benz	SLR Class(315 Mhz)	04-06	35	1090K	502980	1094	502992	9004	489773
M-Benz	SLR Class(433 Mhz)	00-06	35	1090K	502980	1094	502992	9001	545608
M-Benz	SLR Class(315 Mhz)	08-09	53	1040K	502977	1040K	502977	1054	503010
M-Benz	SLR Class(433 Mhz)	08-09	53	1040K	502977	1040K	502977	1049	574586
M-Benz	SLS(433 mhz)	11-13	53	2030K	502970	9066K	648491	28214	296763
Mercury	Grand Marquis	07-10	---	1194	1194 Band	NO	NO	7001/HP	562515
Mercury	Mariner	06-08	---	1194	1194 Band	NO	NO	7001/HP	562515
Mercury	Mariner	09-11	---	VS950	502975	VS950	502975	7001R/HPR	562517
Mercury	Milan	08-09	---	1194	1194 Band	NO	NO	7001/HP	562515
Mercury	Milan	10-11	---	VS950	502975	VS950	502975	7001R/HPR	562517

DILL TPMS APPLICATIONS CHART ©

OE	Model	Model Year	Torque In-Lbs	Dill Kit #	Costco Service Pack #	Valve Stem Replacement	Costco Valve #	Dill Sensor	Costco Sensor #
Mercury	Montego	06-07	---	1194	1194 Band	NO	NO	7001/HP	562515
Mercury	Monterey(315 Mhz)	04-05	44	1060K	502905	NO	NO	7001/HP	562515
Mercury	Monterey	06-07	---	1194	1194 Band	NO	NO	7001/HP	562515
Mercury	Mountaineer(433 Mhz)	02-05	44	1060K	502905	NO	NO	7004	562516
Mercury	Mountaineer	06-10	---	1194	1194 Band	NO	NO	7001/HP	562515
Mercury	Sable	08-09	---	1194	1194 Band	NO	NO	7001/HP	562515
*Redi-Sensor relearn must be performed with scan tool and not magnet.									
Mini	All(433 Mhz)	07-10	35	1090K	502980	1094	502992	1027	562514
Mini	All(433 Mhz) (September 2009)	11-12	35	1090K	502980	1094	502992	9012	574594
Mitsubishi	Eclipse(Alloy)	06-12	45-53	1080K	502913	NO	NO	7001/HP	562515
Mitsubishi	Eclipse(Steel)	06-07	45-53	1130K	502926	NO	NO	7001/HP	562515
Mitsubishi	Endeavor(433 Mhz)	04-06	45-53	1080K	502913	NO	NO	7004	562516
Mitsubishi	Endeavor(Sept +)	06-12	45-53	1080K	502913	NO	NO	7001/HP	562515
Mitsubishi	Galant(433 Mhz)	04-06	45-53	1080K	502913	NO	NO	7004	562516
Mitsubishi	Galant	07-12	45-53	1080K	502913	NO	NO	7001/HP	562515
Mitsubishi	Galant(Steel)	07-12	45-53	1130K	502926	NO	NO	7001/HP	562515
Mitsubishi	i-MiEV	12-13	71	7000K	502973	VS70	707594		
Mitsubishi	Lancer	08-10	71	1050K	502904	NO	NO	dealer must perform relearn	
Mitsubishi	Lancer	10-11	71	7000K	502973	VS70	707594	dealer must perform relearn	
Mitsubishi	Montero	03-05	45-53	1080K	502913	NO	NO	7001/HP	562515
Mitsubishi	Outlander	07-10	71	1050K	502904	NO	NO	dealer must perform relearn	
Mitsubishi	Outlander	10-13	71	7000K	502973	VS70	707594	dealer must perform relearn	
Mitsubishi	Raider(HP)	08-09	53	2030K	502970	9066K	648491	7001/HP	562515
Nissan	350Z	04-06	45-60	1080K	502913	NO	NO	7001/HP	562515
Nissan	350Z	07-09	50-70	2030K	502970	NO	NO	7001/HP	562515
Nissan	370Z	08-10	50-70	2030K	502970	NO	NO	7001/HP	562515
Nissan	370Z	11-13	50-70	1100K	502921	NO	NO	1216	643321
Nissan	Altima	06-10	50-70	2030K	502970	NO	NO	7001/HP	562515
Nissan	Altima	11-12	65	7020K	648487	VS70	707594	7001/HP	562515
Nissan	Armada(Alloy)--SE	05-08	49	1080K	502913	NO	NO	7001/HP	562515
Nissan	Armada(Steel)	05-06	49	1130K	502926	NO	NO	7001/HP	562515
Nissan	Armada-LE	09-13	50-70	2030K	502970	NO	NO	7001/HP	562515
Nissan	Cube	09-10	50-70	2030K	502970	NO	NO	7001/HP	562515
Nissan	Cube	11-13	35	1100K	502921	NO	NO	7001/HP	562515
Nissan	Frontier	03-04	45-60	1080K	502913	NO	NO	7001/HP	562515
Nissan	Frontier(Alloy)	05-08	49	1080K	502913	NO	NO	7001/HP	562515
Nissan	Frontier(Steel)	05-07	49	1130K	502926	NO	NO	7001/HP	562515
Nissan	Frontier(Steel)	09-10	50-70	2030K	502970	NO	NO	7001/HP	562515
Nissan	Frontier	11-13	71	7020K	648487	VS70	707594	7001/HP	562515
Nissan	GT-R	09-13	50-70	2030K	502970	NO	NO	7001/HP	562515
Nissan	Juke--S Model	11	50-70	2030K	502970	NO	NO	7001/HP	562515
Nissan	Juke--S Model	12-13	50-70	1100K	502921	NO	NO	1216	643321
Nissan	Juke--SL & SV Model (CVT)	11-13	50-70	1100K	502921	NO	NO	1216	643321
Nissan	Juke--SL & SV Model (Manual--Pre 3/12)	12	50-70	2030K	502970	NO	NO	7001/HP	562515
Nissan	Juke--SL & SV Model (Manual--Post 3/12)	12-13	50-70	1100K	502921	NO	NO	7001/HP	562515
Nissan	Leaf	11-13	50-70	1100K	502921	NO	NO	1216	643321
Nissan	Leaf (>12/11)	13	71	7000K	502973	VS70	707594		
Nissan	Maxima(Alloy)	06-07	49	1080K	502913	NO	NO	7001/HP	562515
Nissan	Maxima(Post-April)	07-11	50-70	2030K	502970	NO	NO	7001/HP	562515
Nissan	Maxima	12	35	2030K	502970	NO	NO	7001/HP	562515
Nissan	Maxima (>12/11)	12-13	71	7000K	502973	VS70	707594	7001/HP	562515
Nissan	Murano	03-06	45-60	1080K	502913	NO	NO	7001/HP	562515
Nissan	Murano	07-12	50-70	2030K	502970	NO	NO	7001/HP	562515
Nissan	Murano (>11/11)	12-14	35	1100K	502921	NO	NO	7001/HP	562515
Nissan	NV 1500/2500HD/3500HD	12	40	2030K	502970	NO	NO	NEW	N/A
Nissan	Pathfinder	03-04	45-60	1080K	502913	NO	NO	7001/HP	562515
Nissan	Pathfinder(Steel)	04	49	1130K	502926	NO	NO	7001/HP	562515
Nissan	Pathfinder	05-06	49	1080K	502913	NO	NO	7001/HP	562515
Nissan	Pathfinder	07-12	50-70	2030K	502970	NO	NO	7001/HP	562515
Nissan	Pathfinder	13	71	7000K	502973	VS70	707594	5556	
Nissan	Quest(Steel)	04-07	49	1130K	502926	NO	NO	7001/HP	562515
Nissan	Quest(Alloy)	05-06	78	1080K	502913	NO	NO	7001/HP	562515
Nissan	Quest	07-09	50-70	2030K	502970	NO	NO	7001/HP	562515
Nissan	Quest	11-13	50-70	1100K	502921	NO	NO	1216	643321
Nissan	Rogue	08-11	50-70	2030K	502970	NO	NO	7001/HP	562515
Nissan	Rogue (>11/11)	11-13	35	1100K	502921	NO	NO	7001/HP	562515
Nissan	Sentra(Alloy)	07-08	75	1080K	502913	NO	NO	7001/HP	562515

DILL TPMS APPLICATIONS CHART ©

OE	Model	Model Year	Torque In-Lbs	Dill Kit #	Costco Service Pack #	Valve Stem Replacement	Costco Valve #	Dill Sensor	Costco Sensor #
Nissan	Sentra(Steel)	07-12	50-70	2030K	502970	NO	NO	7001/HP	562515
Nissan	Sentra(> 1/12)	13	35	1100K	502921	NO	NO	7001/HP	562515
Nissan	Sentra(> 9/12) without I-KEY	13	65	7000K	502973	VS70	707594	7001/HP	562515
Nissan	Sentra(> 12/12) with I-KEY	13	65	7000K	502973	VS70	707594		
Nissan	Titan(Alloy)	05-07	49	1080K	502913	NO	NO	7001/HP	562515
Nissan	Titan(Steel)	04-05	49	1130K	502926	NO	NO	7001/HP	562515
Nissan	Titan(Steel) (Post April)	07-13	50-70	2030K	502970	NO	NO	7001/HP	562515
Nissan	Versa	07-11	50-70	2030K	502970	NO	NO	7001/HP	562515
Nissan	Versa 1.6S & SV	12-13	65	7000K	502973	VS70	707594	7001/HP	562515
Nissan	Versa 1.6 SL	12-13	65	7000K	502973	VS70	707594		
Nissan	Xterra	03-04	45-60	1080K	502913	NO	NO	7001/HP	562515
Nissan	Xterra	05-06	49	1080K	502913	NO	NO	7001/HP	562515
Nissan	Xterra(Steel)	06-07	49	1130K	502926	NO	NO	7001/HP	562515
Nissan	Xterra	07-12	50-70	2030K	502970	NO	NO	7001/HP	562515
Nissan	Xterra	13	71	7000K	502973	VS70	707594	7001/HP	562515
Pontiac	G3	09	---	VS950	502975	VS950	502975	7001R/HPR	562517
Pontiac	G5	08	80	1050K	502904	NO	NO	7001/HP	562515
Pontiac	G5	09-10	---	VS950	502975	VS950	502975	7001R/HPR	562517
Pontiac	G6(Pre-10/15)	08	80	1050K	502904	NO	NO	7001/HP	562515
Pontiac	G6(Post-10/15)	08-10	---	VS950	502975	VS950	502975	7001R/HPR	562517
Pontiac	G8	08-09	---	VS950	502975	VS950	502975	7001R/HPR	562517
Pontiac	Grand Prix	07-08	80	1050K	502904	NO	NO	7001/HP	562515
Pontiac	Grand Prix	08	---	VS950	502975	VS950	502975	7001R/HPR	562517
Pontiac	Montana	08	80	1050K or 1070K	502904 OR 502911	NO	NO	7001/HP	562515
Pontiac	Solstice	08-09	80	1050K	502904	NO	NO	7001/HP	562515
Pontiac	Torrent	07-09	80	1050K	502904	NO	NO	7001/HP	562515
Pontiac	Vibe	08-10	35	1100K	502921	NO	NO	7002	707597
Pontiac	Wave	08	---	VS950	502975	VS950	502975	7001R/HPR	562517
**The 1050K is to be used on the Siemens sensors and the 1070K is to be used on the Schrader sensors.									
Porsche	911 Carrera(433 Mhz)	05-08	31-40	1090K	502980	1092	502980	9001	545608
Porsche	911 Carrera(433 Mhz) (Post April 2008)	09-14	31-40	1090K	502980	1092	502980	9008	574587
Porsche	911 Carrera(315 Mhz)	05-08	31-40	1090K	502980	1092	502980	9004	489773
Porsche	911 Turbo(433 Mhz)	07-09	31-41	1090K	502980	1092	502980	9001	545608
Porsche	911 Turbo(433 Mhz)	10-14	40	1096	300415	1096	300415	9011	574593
Porsche	911 Turbo(315 Mhz)	07-09	31-43	1090K	502980	1092	502980	9004	489773
Porsche	911 Turbo(315 Mhz)	10-14	31-44	1090K	502980	1092	502980		
Porsche	Boxster(433 Mhz)	05-08	31-40	1090K	502980	1092	502980	9001	545608
Porsche	Boxster(433 Mhz)-- Post November 2008	09-14	31-40	1090K	502980	1092	502980	9008	574587
Porsche	Boxster(315 Mhz)	05-08	31-40	1090K	502980	1092	502980	9004	489773
Porsche	Carrera GT(433 Mhz)	03-06	31-40	1090K	502980	1092	502980	9001	545608
Porsche	Carrera GT(315 Mhz)	04-06	31-40	1090K	502980	1092	502980	9004	489773
Porsche	Cayenne(433 Mhz)	03-06	31-40	1090K	502980	1092	502980	9005	574094
Porsche	Cayenne(315 Mhz)	09-10	31-40	1090K	502980	1092	502980	9004	489773
Porsche	Cayenne(433 Mhz)	07-10	31-40	1090K	502980	1092	502980	9007	571724
Porsche	Cayenne(433 Mhz)	11-13	31-40	1096		1096		9011	574593
Porsche	Cayman(433 Mhz)	05-08	31-40	1090K	502980	1092	502980	9001	545608
Porsche	Cayman(433 Mhz)	09-14	31-40	1090K	502980	1092	502980	9008	574587
Porsche	997 GT3(433 Mhz)	07-09	31-40	1090K	502980	1092	502980	9001	545608
Porsche	997 GT3(433 Mhz)	10-14	31-40	1090K	502980	1092	502980	9008	574587
Porsche	997 GT3(315 Mhz)	07-09	31-40	1090K	502980	1092	502980	9004	489773
Porsche	Panamera(315 Mhz)	10-13	31-40	1090K	502980	1092	502980	9004	489773
Porsche	Panamera(433 Mhz)	10-13	31-40	1090K	502980	1092	502980	9008	574587
Rolls Royce	Phantom(433 Mhz)	07-12	31-40	1090K	502980	1092 or 1094	502980 or 502992	1027	562514
Rolls Royce	Phantom(433 Mhz)	12-14	40	1096		1096		9012	574594
Rolls Royce	Cabrio(433 Mhz)	07-10	31-40	1090K	502980	1092 or 1094	502980 or 502992	1027	562514
Saab	9-3(433 Mhz)	04-07	62	2010K	502930	NO	NO	28078	296755
Saab	9-3(433 Mhz)	08-12	88	2010K	502930	NO	NO		N/A
Saab	9-5(433 Mhz)	04-07	62	2010K	502930	NO	NO	28078	296755
Saab	9-5(433 Mhz)	08-12	88	2010K	502930	NO	NO		N/A
Saab	9-7X(315 Mhz)	05-09	62	1070K	502911	NO	NO	7001/HP	562515
Saturn	Astra(433 Mhz)	08-09	62	2010K	502930	NO	NO	28078	296755
Saturn	Aura(<10/14/07)	07-08	80	1050K	502904	NO	NO	7001/HP	562515
Saturn	Aura(>10/14/07)	08-09	---	VS950	502975	VS950	502975	7001R/HPR	562517

DILL TPMS APPLICATIONS CHART ©

OE	Model	Model Year	Torque In-Lbs	Dill Kit #	Costco Service Pack #	Valve Stem Replacement	Costco Valve #	Dill Sensor	Costco Sensor #
Saturn	Lamda Crossover	07-08	80	1050K or 1070K	502904 OR 502911	NO	NO	7001/HP	562515
Saturn	Outlook	07-08	80	1050K	502904	NO	NO	7001/HP	562515
Saturn	Outlook	09-10	---	VS950	502975	VS950	502975	7001R/HPR	562517
Saturn	Sky	08-09	80	1050K	502904	NO	NO	7001/HP	562515
Saturn	Vue	07-10	---	VS950	502975	VS950	502975	7001R/HPR	562517
**The 1050K is to be used on the Siemens sensors and the 1070K is to be used on the Schrader sensors.									
Scion	tC	06-13	35	1100K	502921	NO	NO	7002	707597
Scion	FR-S	13	35	1100K	502921	NO	NO	1218	643351
Scion	iQ	12-13	35	1100K	502921	NO	NO	7002	707597
Scion	xB	08-12	35	1100K	502921	NO	NO	7002	707597
Scion	xD	08-13	35	1100K	502921	NO	NO	7002	707597
Smart	Fortwo(433 Mhz)	08	53	1040K	502977	1040K	502977	1049	574586
Smart	Fortwo(433 Mhz)	08-13	53	2030K	502970	9066K	648491	28214	296763
Subaru	B9 Tribeca	06-07	66	1080K	502913	NO	NO	20081	296734
Subaru	BRZ	13	35	1100K	502921	NO	NO	1218	643351
Subaru	Forester	08-13	---	VS950	502975	VS950	502975	28203	296761
Subaru	Impreza	08-13	---	VS950	502975	VS950	502975	28203	296761
Subaru	Legacy	04-07	66	1080K	502913	NO	NO	20081	296734
Subaru	Legacy	08-13	---	VS950	502975	VS950	502975	28203	296761
Subaru	Outback	04-07	66	1080K	502913	NO	NO	20081	296734
Subaru	Outback	08-13	---	VS950	502975	VS950	502975	28203	296761
Subaru	Tribeca	08-13	---	VS950	502975	VS950	502975	28203	296761
Suzuki	Equator	09-13	68	2030K	502970	NO	NO	7001/HP	562515
Suzuki	Forenza	07-08	---	VS950	502975	VS950	502975	7001R/HPR	562517
Suzuki	Grand Vitara	07-13	80	2010K	502930	NO	NO	20087	296736
Suzuki	Kizashi	10-13	62	7000K	502973	VS70	707594	7001/HP	562515
Suzuki	Reno	07-08	---	VS950	502975	VS950	502975	7001R/HPR	562517
Suzuki	SX4	07-12	80	2010K	502930	NO	NO	20087	296736
Suzuki	Verona	05-06	80	2010K	502930	NO	NO	20082	296735
Suzuki	XL-7	05-06	80	2010K	502930	NO	NO	20087	296736
Suzuki	XL-7	07-09	62	1050K	502904	NO	NO	7001/HP	562515
Tesla	ALL	10-13	40-50	2020K	502931			2112	
Toyota	4 Runner	03-13	35	1110K	502923	NO	NO	7002	707597
Toyota	Avalon	07-13	35	1100K	502921	NO	NO	7002	707597
Toyota	Avalon (post 11/12)	13	35	1100K	502921	NO	NO	1218	643351
Toyota	Camry	07-11	35	1100K	502921	NO	NO	7002	707597
Toyota	Camry	12-13	35	1100K	502921	NO	NO	1218	643351
Toyota	Corolla	07-13	35	1100K	502921	NO	NO	7002	707597
Toyota	FJ Cruiser	08-13	35	1100K	502921	NO	NO	7002	707597
Toyota	Highlander	07-13	35	1100K	502921	NO	NO	7002	707597
Toyota	Land Cruiser	05-13	35	1100K	502921	NO	NO	7002	707597
Toyota	Matrix	07-13	35	1100K	502921	NO	NO	7002	707597
Toyota	Prius / Prius V	06-13	35	1100K	502921	NO	NO	7002	707597
Toyota	Prius C	12-13	35	1100K	502921	NO	NO	1218	643351
Toyota	RAV 4	06-13	35	1100K	502921	NO	NO	7002	707597
Toyota	RAV4(Post 1/13)--Smart Key	13	35	1100K	502921	NO	NO	1218	643351
Toyota	Sequoia(20 Degrees)	04-07	35	1110K	502923	NO	NO	7002	707597
Toyota	Sequoia(40 Degrees)	04-07	35	1110K	502923	NO	NO	7002	707597
Toyota	Sequoia(20 Degrees)	08-13	35	1110K	502923	NO	NO	7002	707597
Toyota	Sequoia(40 Degrees)	08	35	1110K	502923	NO	NO	7002	707597
Toyota	Sienna(20 Degrees)	06-13	35	1110K	502923	NO	NO	7002	707597
Toyota	Solara	06-08	35	1100K	502921	NO	NO	7002	707597
Toyota	Tacoma(20 Degrees)	05-06	35	1110K	502923	NO	NO	7002	707597
Toyota	Tacoma(40 Degrees)	05-13	35	1110K	502923	NO	NO	7002	707597
Toyota	Tacoma(20 Degrees)	07-13	35	1100K	502921	NO	NO	7002	707597
Toyota	Tundra(20 Degrees)	05-06	35	1110K	502923	NO	NO	7002	707597
Toyota	Tundra(40 Degrees)	05-06	35	1110K	502923	NO	NO	7002	707597
Toyota	Tundra(20 Degrees)	06-13	35	1110K	502923	NO	NO	7002	707597
Toyota	Tundra(40 Degrees)	06-11	35	1110K	502923	NO	NO	7002	707597
Toyota	Venza	09-13	35	1100K	502921	NO	NO	7002	707597
Toyota	Yaris	07-11	35	1100K	502921	NO	NO	7002	707597
Toyota	Yaris	12-13	35	1100K	502921	NO	NO	1218	643351
Volkswagen	Beetle	08-10	71	1030K	502902	NO	NO	1053	506565
Volkswagen	CC	09-10	71	1030K	502902	NO	NO	1053	506565
Volkswagen	CC	12-13	35	1096	300415	1096	300415	9013	728983
Volkswagen	EOS	07-12	71	1030K	502902	NO	NO	1053	506565

DILL TPMS APPLICATIONS CHART ©

OE	Model	Model Year	Torque In-Lbs	Dill Kit #	Costco Service Pack #	Valve Stem Replacement	Costco Valve #	Dill Sensor	Costco Sensor #
Volkswagen	GLI	08-09	71	1030K	502902	NO	NO	1053	506565
Volkswagen	Golf	10	71	1030K	502902	NO	NO	1053	506565
Volkswagen	GTI(Standard Hex)	06-11	71	1030K	502902	NO	NO	1053	506565
Volkswagen	GTI(O-ring Hex)	06-07	71	1031K	574596	NO	NO	1041	574265
Volkswagen	Jetta(Standard Hex)	06-10	71	1030K	502902	NO	NO	1053	506565
Volkswagen	Jetta Sportwagen	13	35	1096	300415	1096	300415		
Volkswagen	Passat(Standard Hex)	06-10	71	1030K	502902	NO	NO	1053	506565
Volkswagen	Passat(O-ring Hex)	06-08	71	1031K	574596	NO	NO	1041	574265
Volkswagen	Passat(433 Mhz)	11-13	35	1096	300415	1096	300415	9013	728983
Volkswagen	Phaeton(433 Mhz) (thru May 2007)	02-07	35	1090K	502980	1092	502980	9001	545608
Volkswagen	Phaeton(433 Mhz) (June 2007)	07-10	35	1090K	502980	1092	502980	9007	571724
Volkswagen	Phaeton(433 Mhz)	11-13	35	1096		1096		9011	574593
Volkswagen	Phaeton(315 Mhz)	03-07	35	1090K	502980	1092	502980	9004	489773
Volkswagen	R32	08	71	1030K	502902	NO	NO	1053	506565
Volkswagen	Rabbit(Standard Hex)	06-09	71	1030K	502902	NO	NO	1053	506565
Volkswagen	Rabbit(O-ring Hex)	06-07	71	1031K	574596	NO	NO	1041	574265
Volkswagen	Routan(433 Mhz)	09-10	71	1050K	502904	NO	NO	7004	562516
Volkswagen	Routan(433 Mhz)	11	---	VS950	502975	VS950	502975	9398	518228
Volkswagen	Tiguan	09-11	71	1030K	502902	NO	NO	1053	506565
Volkswagen	Tiguan	12-13	35	1096	300415	1096	300415	9013	728983
Volkswagen	Touareg(433 Mhz)	04-06	35	1090K	502980	1092	502980	9005	574094
Volkswagen	Touareg 2(433 Mhz)	07-10	35	1090K	502980	1092	502980	9007	571724
Volkswagen	Touareg 2(433 Mhz)	11	35	1090K	502980	1092	502980	9011	574593
Volvo	C30(433 Mhz)	07-10	71	1050K	502904	NO	NO	1044	518230
Volvo	C30(433 Mhz)	10-13	71	7020K	648487	VS70	707594	1044	518230
Volvo	C70(433 Mhz)	07-10	71	1050K	502904	NO	NO	1044	518230
Volvo	C70(433 Mhz)	10-13	71	7020K	648487	VS70	707594	1044	518230
Volvo	S40(433 Mhz)	07-10	71	1050K	502904	NO	NO	1044	518230
Volvo	S40(433 Mhz)	10-12	71	7020K	648487	VS70	707594	1044	518230
Volvo	S60(315 Mhz)	04-10	44	2010K	502930	NO	NO	20156	296747
Volvo	S60(433 Mhz)	11-13	71	7020K	648487	VS70	707594	1044	518230
Volvo	S80(315 Mhz)	04-07	44	2010K	502930	NO	NO	20156	296747
Volvo	S80(433 Mhz)	07-10	71	1050K	502904	NO	NO	1044	518230
Volvo	S80(433 Mhz)	10-13	71	7020K	648487	VS70	707594	1044	518230
Volvo	V50(433 Mhz)	08-10	71	1050K	502904	NO	NO	1044	518230
Volvo	V50(433 Mhz)	10-11	71	7020K	648487	VS70	707594	1044	518230
Volvo	V70(315 Mhz)	04-07	44	2010K	502930	NO	NO	20156	296747
Volvo	V70(433 Mhz)	08-10	71	1050K	502904	NO	NO	1044	518230
Volvo	XC60	10	44	2010K	502930	NO	NO	20156	296747
Volvo	XC60	11-13		7020K	648487	VS70	707594	1044	518230
Volvo	XC70(315 Mhz)	04-07	44	2010K	502930	NO	NO	20156	296747
Volvo	XC70(433 Mhz)	08-10	71	1050K	502904	NO	NO	1044	518230
Volvo	XC70(433 Mhz)	10-13	71	7020K	648487	VS70	707594	1044	518230
Volvo	XC90(315 Mhz)	05-13	44	2010K	502930	NO	NO	20156	296747
Volvo	XC90(433 Mhz)	08	71	1050K	502904	NO	NO	1044	518230
Volvo	XC90(433 Mhz)	10-11	71	7020K	648487	VS70	707594	1044	518230

DISCLAIMER: The data presented in this document is accurate to the best of our knowledge and is regularly updated with the latest data available in the marketplace.